



**Composites®
International**

Ideas For Meaningful Results.

idicomposites.com

TROUBLESHOOTING MOLDING PROBLEMS

Molding Guide for BMC & SMC

IDI Composites International
June, 2017

Table of Contents

Blisters.....	3
Bond Failure	4
Bond Readout	5
Chip	6
Contamination	7
Crazing (Surface Cracks).....	8
Dieseling.....	9
Dirt	10
Dull Surface	11
Ejector Cracks.....	12
Fiber Pull	13
Fiber Tear	14
Finger Tracks	15
Fish Eye	16
Flow Marks.....	17
Fractures	18
Gouge.....	19
Hanging Fibers.....	20
Knit Lines	21
Laking	22
Mold Marks.....	23
Molded Poly	24
Non-Fill.....	25
Paint Sags	26
Porosity	27
Pre Gel.....	28
Resin Rich	29
Rib, Pin and Boss Readout	30
Ripple	31
Sand Through	32
Sander Scratches.....	33
Scratch.....	34
Separation (Phasing)	35
Scumming.....	36
Sink Marks.....	37
Sticking	38
Streaking (Abrasion).....	39
Surface Waviness	40
Undercure	41
Warpage (Dimensional Error)	42
Water Spots	43
White Spots.....	44

Blisters

A blister is a delamination that produces a bulge on the surface of the part. This bulge is usually regular in shape and can range in size from 1/8 to 10 inches. A blister is caused by the presence of gases under pressure within the substrate, forcing the skin away from the glass. Can be seen on painted or unpainted parts.

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Insufficient glass wet out with resin (dry glass) • Foreign objects/contamination (film, flash, etc.) in or on the charge • Wrinkles/pockets in discontinuous surface of SMC charge pattern
<i>Process</i>	<ul style="list-style-type: none"> • Adding small SMC pieces to charge pattern which trap air • Insufficient pressure on SMC during cure cycle • Oven temperature heat-up rate too fast, especially in combination with a high moisture content part • Improper charge patten (too large, rolled or folded) • Mold temperature out of spec • Vacuum too low; improper vacuum cycle • Low cure time (under cure) • Press closure speed to fast (air trapped in laminate)
<i>Tooling</i>	<ul style="list-style-type: none"> • Mold shear edge is too tight (not allowing air to bleed out) • Tool Deflection

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Check for fiberglass wet out • Check material for contaminants and check for moisture contamination • Evaluate viscosity levels affect on blisters, look at high, medium and low • Use less reactive catalyst • Select different shrink additives • Verify material is not dried out
<i>Process</i>	<ul style="list-style-type: none"> • Increase material flow distance • Increase molding pressure • Pyramid charge in center of the tool • Load pattern, location, size, thickness • Appropriate vacuum amount and timing (position) • Appropriate press closure speeds • Appropriate mold temperatures • Appropriate cure time • Do not use makeup pieces in the charge • Be certain mold shears are clean with at least 0.004" of flash
<i>Tooling</i>	<ul style="list-style-type: none"> • Check for mold deflection • Check for Platen parallelism

Bond Failure

Failure of a bonded assembly, usually at the interface of the adhesive and the substrate	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Out of spec SMC
<i>Process</i>	<ul style="list-style-type: none"> • Gel time of adhesive too short to permit proper bonding • Bond not fully cured before clamps are removed • Improperly prepared bond surfaces • Mix ratio of the two-component adhesive is off • Moisture contamination of adhesive or surface to be bonded • Out of spec adhesive • Excessive internal or external mold release in/on the SMC • Shift between inner and outer panels during curing of the adhesive • Incompatible substrate and bond material • Introduction of air into dispense system causing gaps, ratio variations • Improper cure cycle • Improper heating during bond cycle
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Improve QC of adhesive material • Fully cure adhesive before pressure or clamping is removed • Properly prepare surfaces to be bonded • Ensure that periodic check of the mix ratio is performed • Control temperature of adhesive • Do not use external mold release on bond areas
<i>Tooling</i>	

Bond Readout

Bond readout is a surface distortion similar to a hump or sink that occurs over a bond line	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Mismatch of compliance between outer panel, inner panel and adhesive • Incompatible thermal expansion coefficients between the SMC and the adhesive • Excessive shrinkage of the adhesive during the fixturing and curing cycles • Excessive fixturing pressure induced due to part mismatch of the outer/inner panels and the bond line standoffs • Excessive fixturing temperature due to non-uniform heating • Hot spots from adhesive exothermic reaction due to non-uniform adhesive thickness • Bond gap thick above 1.5 mm • Bond gap thin below 0.5 mm • Outer panel thin, less than 2.0 mm • Inner thickness above maximum
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Increase the thickness of the bonding area of the appearance panel or select a more flexible adhesive • Match the thermal expansion coefficients between the substrate and the adhesive as much as possible • Select an adhesive with minimum polymerization shrinkage • Obtain matched outer/inner panels through better tooling • Eliminate bond line standoffs • Use closed-loop feedback temperature control system for tighter temperature variation tolerance of the fixture • Minimize and control clamp pressure • Mold warp-free parts; do not use adhesive bond fixture to straighten parts • Check adhesive thickness to specification • Check outer thickness to specification • Check inner thickness to specification
<i>Tooling</i>	

Chip

A chip is damage to the surface of the part that results in small (less than /2 inch) missing pieces. A chip usually occurs near the edge, and since it is nonstructural, it usually is repairable

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Resin-rich edge
<i>Process</i>	<ul style="list-style-type: none"> • Rough handling • Rough bypass • Shipping racks lack necessary padding • No use of in-process racks (parts are stacked on each other) • Squared edge on part at mating surface with adjacent parts
<i>Tooling</i>	<ul style="list-style-type: none"> • Improperly designed secondary fixtures (non padded in all necessary areas) • Mold defects on edges or flash stuck to shear edge

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Increase compound viscosity
<i>Process</i>	<ul style="list-style-type: none"> • Utilize transfer lines and other hands-off processing techniques • Train workers in proper handling techniques • Improve shipping procedures and monitor part quality • Improve shipping rack repair procedures • Add external mold release and clean • Slow ejector speed • Slow press closure rate • Relocate charge • Decrease molding pressure
<i>Tooling</i>	<ul style="list-style-type: none"> • Design secondary fixtures properly and coat them with soft materials to absorb shocks • Preventative maintenance on molds and fixtures • Periodically clean flash on shear edges and gummy deposits of styrene • Polish tool surface

Contamination

Foreign material in the laminate	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Foreign material in SMC compound or raw materials
<i>Process</i>	<ul style="list-style-type: none"> • Foreign material from the molding presses
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Check for foreign materials in molding compound and cut out if necessary • Check for foreign materials in raw materials
<i>Process</i>	
<i>Tooling</i>	

Crazing (Surface Cracks)

<p>Craze cracks are hairline cracks that do not go through the entire thickness of the part. These cracks usually occur in groups. Craze cracks can appear similar to porosity on painted parts.</p>	
<p>Probable Cause</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Mechanical overstressing caused by part sticking in the mold or rough handling • Poor material flow pattern around mash-offs, core pins, mold outs • Thermal stresses induced by mold temperature or by non-uniform part cool down • Charge pattern changed by adding small pieces to make up weight • Ejector pins • Thick-to-thin wall thickness variation
<i>Tooling</i>	<ul style="list-style-type: none"> • Secondary fixtures improperly designed • Thick-to-thin wall thickness variation • Ribs too thick with respect to wall thickness • Cored holes or slides too low from designated surface position
<p>Corrective Action</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Train workers in proper handling techniques • Cool parts at a uniform rate • Design charge pattern to minimize improper flow behavior • Do not use makeup pieces in charge pattern • Minimize mash-offs • Slow ejection system to reduce ejector pin crazing • Increase differential temperature between core and cavity
<i>Tooling</i>	<ul style="list-style-type: none"> • Design secondary fixtures so they do not induce stress on the part and coat them with soft materials to absorb shock • Polish shear edges of cavity, eliminate back draft or undercuts • Ensure smooth transition from thick to thin sections

Dieseling

Dieseling is a burnt spot on the laminate, often accompanied by non-fills	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Air entrapped in the tool which burns
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Increase material flow distance • Slow press closure • Vary mold temperature differential • Increase shear opening (assumes dieseling occurs near the shear edge) • Add vented ejector pins
<i>Tooling</i>	

Dirt

Dirt is a particulate contaminate under or in any paint film that shows up as a raised bump of the cured paint film.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Dirt on parts as received • Dirt created by repairing SMC defects • Dirt on the paint rack that is not washed off • Dirt, hair, fibers, etc. from workers • Improper paint shop cleanliness • De-ionized rinse out of spec
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Installation of appropriate power washer • Automate paint operations • Proper maintenance of paint equipment and paint booth • Remove and clean overspray on the paint racks per agreed-upon schedule • Analyze dirt particles to accurately determine source • Clean overhead conveyor • Improve paint shop cleanliness procedures
<i>Tooling</i>	

Dull Surface

Loss of gloss on overall part surface	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • High shrinkage
<i>Process</i>	<ul style="list-style-type: none"> • Under cure • Loss of pressure
<i>Tooling</i>	<ul style="list-style-type: none"> • Unacceptable tool surface
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Check for catalyst level • Check resin reactivity • Select different shrink additives or levels
<i>Process</i>	<ul style="list-style-type: none"> • Increase mold temperature • Increase cure cycle • Increase molding pressure • Maintain constant material pressure in press
<i>Tooling</i>	<ul style="list-style-type: none"> • Polish and buff tool surface • Chrome plate tool surface

Ejector Cracks

Ejector cracks are small, visible surface cracks on the cavity side surface of the molded part. These are often found on the opposite side of the part above an ejector pin. A crack located on the surface of the laminate that does not extend completely through the substrate.

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Resin Reactivity
<i>Process</i>	<ul style="list-style-type: none"> • The part is sticking to the core • The part is under-cured • Cure time is too low • Mold temperature is too low • Insufficient release agent • The ejector pin is placed in a poor location, too few fins or too small a diameter
<i>Tooling</i>	<ul style="list-style-type: none"> • Ejection system is too fast • Blocked air to popper passage (partial) • Improperly sized air supply line to air popper • Ejection system leading air popper blow off • Excess flash around ejection pin • Undercuts along shear (acting as “hangers”)

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Use less reactive catalyst
<i>Process</i>	<ul style="list-style-type: none"> • Check temperature and cure times • Place ejector pins in areas least sensitive such as below ribs or bosses, increase diameter or number of pins • Add vented ejector pins • Verify correct load pattern weight • Add external mold release, mold one part, then discard that part • Clean shear edges
<i>Tooling</i>	<ul style="list-style-type: none"> • Slow ejection system • Check mold for undercuts • Alleviate stresses holding the part too tight to the core (undercuts, etc) • Proper sequencing of air popper system • Inspect mold for biased ejection, install flow control or dividers • If ejectors are on angled surface add skid grooves to top of ejector pin

Fiber Pull

Fiber Pull is a depression left by removing or loosening of fiberglass strands located near the surface of the laminate.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Sticking
<i>Process</i>	<ul style="list-style-type: none"> • Flash buildup on the by-pass
<i>Tooling</i>	<ul style="list-style-type: none"> • Worn by-pass
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Add external mold release and clean by-pass • Vary mold temperature differential (normally narrow the difference) • Decrease by-pass opening • Correct ejector action (are all ejector pins working) • Slow ejector speed
<i>Tooling</i>	

Fiber Tear

Fiber tear is a surface defect caused by fibers tearing away part of the surface resin. These defects always occur near the shear edge of a part.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Improper deflashing of the part • Ejector speed too fast • Charge weight too high • Mold temperature differential incorrect • Molding pressure too high • Molding viscosity too low • Shear edge temperature variance too liberal (causing excess flash/leakage) • Molding press strip speed too fast • Flow parallel to shears
<i>Tooling</i>	<ul style="list-style-type: none"> • Improperly fit or worn shear edges
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Use sandpapers, file or automatic router to deflash instead of a knife • Closer inspection of punched and drilled holes • Use high technology process such as router, water jet, laser or ultrasonics to perform deflash, punch and drill operations • Verify correct load pattern weight • Verify appropriate temperature differential between core and cavity • Verify appropriate molding temperature • Slow ejector speed • Adjust charge to minimize flow parallel to shears
<i>Tooling</i>	<ul style="list-style-type: none"> • Maintain proper shear edge on molds to minimize flash

Finger Tracks

Finger tracks are shallow groves in the surface that show up after prime or top coat. These grooves are usually the width of a finger.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Sanding the surface without a block or backup pad. The pressure directly under the fingers removes more material than between the fingers and leaves tracks that show up on the painted surface • It is generally accepted that the eye can detect surface depressions of 0.0004 inches or greater over a one-inch span
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Always use block or pad when sanding the surface • Develop sanding and feathering techniques that blend surface changes over large areas • Use 400 grit or finer sandpaper
<i>Tooling</i>	

Fish Eye

A fish eye is a circular or elliptical depression in the primer. There is not any penetration into the substrate. Fish eyes are usually caused by some type of surface contamination

Probable Cause

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Oil, grease or silicone contamination in paint system, air feed, paint conveyor line or in the paint itself • Rags containing oil or oil byproducts • Excess mold release at source • Insufficient cleaning of the part • Overspray of primer • Mismatch of solvent with paint or prime system • Ensure parts are not being sprayed or dripped on at press by hydraulic oils (if so, with 50% IPA and 50% DI water)
<i>Tooling</i>	

Corrective Action

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Do not use silicone-containing hand creams or lubricants during handling at press-side or bonding • Properly installed power washer for all SMC parts • Proper maintenance of equipment (filters, etc.) • Ensure proper use of oils and lubricants in the paint shop • Proper QC procedures on all paint materials • Fish eye reducing additives to paint are available.
<i>Tooling</i>	

Flow Marks

Flow marks is the visual orientation of fiberglass strands on the part surface	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Flow condition
<i>Tooling</i>	<ul style="list-style-type: none"> • Tool design
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Evaluate molding viscosity effect • Select different shrink additives or levels
<i>Process</i>	<ul style="list-style-type: none"> • Decrease material flow distance • Relocate charge pattern • Increase press closure rate
<i>Tooling</i>	<ul style="list-style-type: none"> • Change part wall thickness

Fractures

A Fracture is a structural failure in a part which extends complete through the substrate	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Insufficient glass reinforcement • Sticking or wedging of part in mold
<i>Process</i>	<ul style="list-style-type: none"> • Mechanical hang-up from flow related knit lines • Rough handling • Poor material flow pattern around mash-offs, etc. • Charge pattern change by adding small pieces to produce proper weight • In process racks not used or poor quality secondary fixtures • Press opens askew • Poor part design (if every part is cracked) • Improper combination of drill speed and feed rate • Shipping damage • Heavier shear on one edge • Dull drill bit or worn out sleeve • Undercut at parting lines or undercut in the mold • Shears too tight • Cure time too short • Parallelism of ejectors
<i>Tooling</i>	<ul style="list-style-type: none"> • Improperly-designed secondary fixtures or tooling
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Control SMC sheet weight to allow use of automatic cutting of charge patterns • Use QC on SMC glass content • Check SMC flow
<i>Process</i>	<ul style="list-style-type: none"> • Train workers in proper handling techniques • Reduce material flow distance (reduce the flow front) • Design charge pattern to minimize improper flow behavior • Do not use make-up pieces in charge patterns • Properly support part in shipping containers • Evaluate proper paint rack design • Check shears • Change drill bit or sleeve • Eliminate any undercuts in the mold • Increase cure time • Slow ejector speed • Vary mold temperature differential • Add vented ejector pins • Relocate charge
<i>Tooling</i>	<ul style="list-style-type: none"> • Design secondary fixtures so that they do not induce stress in the part • Draw polish shear edges in the cavity • Use parallelism control on the press • Change part wall thickness

Gouge

A gouge is a long, deep depression in the surface, severe enough to require a repair procedure. Gouges can be several thousands of an inch deep.

Probable Cause

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Rough handling • Improperly designed secondary fixtures (not padded in all necessary areas) • Mold defects on edges or flash stuck to shear edge • Shipping racks lack necessary padding • No use of in-process racks (parts are stacked on each other) • Square edge on part at mating surface with adjacent parts
<i>Tooling</i>	

Corrective Action

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Investigate potential source for gouges in process and correct • Train workers in proper handling techniques • Design secondary fixtures properly and coat them with soft materials to absorb shocks • Preventative maintenance on molds and fixtures • Periodically clean flash on shear edges • Improve shipping rack repair procedures • Utilize transfer lines and other hands off processing techniques • Repair using approved repair procedure
<i>Tooling</i>	

Hanging Fibers

<p>Hanging fibers are glass fibers that are left hanging from the part after a deflashing, hold piercing or drilling operation. These fibers cause dirt to be carried into the paint shop.</p>	
<p>Probable Cause</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Dull or improperly fit secondary tooling (bits, mash-offs, punches, etc.) • Improper sanding to remove fibers
<i>Tooling</i>	<ul style="list-style-type: none"> • Dull deflashing tool
<p>Corrective Action</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Closer inspection of pierced and drilled holes • Use high technology process such as router/drill bit design, water jet, laser or ultrasonics to perform deflash, punch and drill operations.
<i>Tooling</i>	<ul style="list-style-type: none"> • Proper maintenance program need for molds, pierce dies and secondary tools.

Knit Lines

<p>Knit line is a term for the molding condition which relates to oriented fiber patterns in the molded part. The knit line usually occurs at the edges or corners of the part furthest from the charge placement position. It is an extremely weak area in the molded part resulting from two flow fronts meeting.</p>	
<p>Probable Cause</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Flow fronts from different charge pattern pieces • Too far of a distance for the SMC to flow • Charge pattern position • Incorrect rate of tonnage build • Spiral flow of SMC to high/low • Mold temperatures too high
<i>Tooling</i>	<ul style="list-style-type: none"> • Mold design (deep vertical walls), etc.
<p>Corrective Action</p>	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Appropriate load placement • Proper press closure • Proper load pattern dimensions • Consistent tonnage build • Check oil level in press • Place charge directly over critical or knit line area if possible • Decrease closure speed (reduce amount of orientation) • Eliminate separate charges if possible • Verify correct molding temperature
<i>Tooling</i>	<ul style="list-style-type: none"> • Optimize mold design for best flow conditions

Laking

Laking is an irregular dull area on the surface of the part. The dull area may be associated with porosity. Laking can also be noticed after prime as “soak-in”	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Differential shrinkage
<i>Process</i>	<ul style="list-style-type: none"> • Too low a pressure on the part during molding (usually on vertical walls) • Molding on stops • Load pattern weight too low • Under-cured part • Cold spots on mold
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Select different shrink additives and/or levels
<i>Process</i>	<ul style="list-style-type: none"> • Maintain pressure on material during molding • Do not mold on stops or flash • Verify load weight is correct and not too low • Verify mold temperatures • Increase pressing speed
<i>Tooling</i>	<ul style="list-style-type: none"> • Equip press with parallelism control

Mold Marks

A mold mark is a lump, depression or line that occurs in the same location of every part due to a damaged mold	
Probable Cause	
<i>Material</i>	
<i>Process</i>	
<i>Tooling</i>	<ul style="list-style-type: none"> • Damage to the cavity of the mold due to insufficient protection • Stuck parts that require scraping off the mold • Improper tools used to clean the mold • Thickness variation flowing thin to thick causing tool wear • Hard metal object molded into part causing mold damage
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Proper QC of SMC materials will reduce the sticking of parts
<i>Process</i>	
<i>Tooling</i>	<ul style="list-style-type: none"> • Repair molds as required • Regular maintenance program for molds • Make sure all cutting utensils are made from soft materials that will not damage the mold surface • Make sure all employees use only copper, brass, wood or plastic tools to scrape the mold surface • Wire down all loose items on the cutting table and loading/unloading equipment • Protect mold surface in transport and storage • Automation should be constructed from aluminum or other soft materials

Molded Poly

Irregular shaped, small depressions on the surface of a part shaped like carrier film chips, but recessed into the substrate. These depressions are normally the colour of the film.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Pieces of carrier film that are molded into the SMC part
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Make sure that all carrier film is removed from the charge, especially when automatic film stripping is not used. • Proper repair procedure required • Frequent changing of blades to ensure clean cuts • Check for proper slitter cutter alignment to shear guide. Improper alignment will cause a small strip to adhere to the edge of the SMC unnoticed.
<i>Tooling</i>	

Non-Fill

A non-fill is a severe void in the laminate. It is an incomplete part that must be scrapped	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Tonnage too low • Mold temperatures too high • Not enough SMC charge weight • Molding on stops • Press closure too slow (tonnage build rate too slow) • Mold temperatures of cavity and core are too close (no flash) • Flash/debris on the mold shears/stops • SMC charge sits on mold too long before closure • SMC charge has to flow too far
<i>Tooling</i>	<ul style="list-style-type: none"> • Tool or platen deflects
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Decrease molding viscosity • Use less reactive catalyst
<i>Process</i>	<ul style="list-style-type: none"> • Verify parameters to control plan/process sheet (tonnage, load pattern, load placement, temperature, closure speeds) • Check SMC spiral flow • Verify molding off stops • Clean mold shears/stops • Check for deflection • Monitor SMC viscosity build • Verify weight scales are correct • Increase molding pressure • Increase closure speed • Ensure charge weights are balanced • Decrease material flow distance • Check oil level in press • Vent ejector pins and/or add vented ejector pins • Shorten tool load time
<i>Tooling</i>	<ul style="list-style-type: none"> • Blend core half to reduce thin to thick flow restrictions in area of non-fill

Paint Sags

A sag is excess paint on a part that shows itself as a hump or ripple that distorts the surface.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Oven temperature too low • Viscosity of paint too low, too much solvent • Film build too thick • Spray gun too close to part being painted • Inconsistent sanding of parts to be reworked (causing sags when painting with electrostatics)
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • QC paint viscosity on each shift • Monitor and control ultimate over temperature and heat up rate • Do not allow painters to get ahead or behind job sequence • Instruct painters on proper spray techniques • Preventative maintenance of spray equipment • Implement automatic paint spraying equipment • Verify appropriate air pressure • Verify appropriate paint pressure • Increase distance between part and gun • Use more coats of paint to get desired film build • Thoroughly scuff sand reworks prior to paint.
<i>Tooling</i>	

Porosity

Porosity is an observable or unobservable condition in any part. It consists of a cluster of holes that usually occurs when trapped air escapes during the molding process. This cluster usually covers an area no larger than a quarter, but can be larger, and can occur as a single hole. Unfilled porosity creates a crater-type condition on a top coated part

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Excess styrene loss
<i>Process</i>	<ul style="list-style-type: none"> • Insufficient flow of the SMC; too large/small a charge pattern • Pre-gel • Flash on shear edge prevents adequate venting of gasses • Insufficient pressure on material during molding • Improper press closure speed • Mold temperature too high • Vacuum too low; improper vacuum cycle • Undercure • Low charge weight • Adding small SMC pieces to charge pattern • Too many plies • Molding on stops • Moisture contamination
<i>Tooling</i>	

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Evaluate viscosity level • Verify material is not dried out
<i>Process</i>	<ul style="list-style-type: none"> • Verify vacuum amount and timing • Verify load pattern location, size, thickness • Verify appropriate press closure speeds • Verify appropriate temperatures • Verify molding off stops • Make sure mold shears are clean • Increase material flow distance • Minimize number of plies in charge • Check charge weight • Check molding pressure • Clean mold stops
<i>Tooling</i>	<ul style="list-style-type: none"> • Change part wall thickness

Pre Gel

Pre-gel causes localized areas of dull, rough, porosity, usually with discoloration	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Too reactive resin • Too reactive catalyst
<i>Process</i>	<ul style="list-style-type: none"> • Slow closure rate
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Check resin reactivity • Use less reactive catalyst
<i>Process</i>	<ul style="list-style-type: none"> • Shorten tool loading time • Increase press closure rates • Decrease mold temperature
<i>Tooling</i>	

Resin Rich

An area in the part where fiberglass strands content is low.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Resin is not carrying fiberglass strands
<i>Process</i>	
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Increase material molding viscosity
<i>Process</i>	<ul style="list-style-type: none"> • Relocate charge pattern • Decrease material flow distance • Slow pressure closure rate
<i>Tooling</i>	

Rib, Pin and Boss Readout

A surface depression located over ribs, bosses, ejector pins or thick sections of the part that appear as a lighter color resulting in read through.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Lack of material flow • Lack of cavity/core temperature differential • Lack of a tonnage “bump” (decrease molding pressure after 30 seconds into cycle)
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Increase material flow distance (do not load over a boss) • Increase mold temperature differential (the hotter appearance side will gel slightly faster and will reduce the amount of sink) • Reduce tonnage after mold fill (high tonnage held through the cure cycle increases sink. Reduce tonnage by 25% to 30% after 30 seconds.
<i>Tooling</i>	

Ripple

Severe short-term waves in the SMC, almost always on the edge of a part or vertical walls.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Improper viscosity • Material too old and will not flow properly • Higher paste shrinkage • Improperly matured SMC • Extremely high-flowing SMC
<i>Process</i>	<ul style="list-style-type: none"> • Inconsistent force on the material during molding • Charge pattern placed or cut improperly • Temperature of mold too high or dropped temperature zone of mold • Improper closure speed • Abrupt thick-to-thin flow condition • Reflow of material due to non-parallel closure (leveling)
<i>Tooling</i>	<ul style="list-style-type: none"> • Mold not centered to press platen • Flow turbulence resulting from tool design
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Investigate viscosity of paste • Verify SMC is within appropriate spiral flow • Investigate past shrinkage
<i>Process</i>	<ul style="list-style-type: none"> • Increase tonnage • Decrease material flow distance • Verify charge weight • Verify molding off stops • Monitor and control mold temperatures to specs
<i>Tooling</i>	<ul style="list-style-type: none"> • May need to offset mold • Modify tooling

Sand Through

A sand through is a break through the primer surface resulting from a sanding operation.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Localized sanding that is deeper and more severe than is necessary (finger sanding) • Tipping power sander to cut deeper in one area to remove dirt or other localized defects • Sanding with too course a sandpaper
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Always block sand defects • Repair mold when mold marks appear to minimize the amount of sanding • Goal is to avoid using sandpaper • Eliminate use of power sanders • Use only 400-grit or finer sandpaper
<i>Tooling</i>	

Sander Scratches

Scratches in the substrate result from a sanding operation. These scratches usually appear as very fine circular scratches.	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Sanding curved areas of part with a flat sander • Improper grit size paper • Sanding Class “A” surface to remove die marks • Repair procedures for all defects • Poor flash removal methods which require additional sanding • Excessive loading of sandpaper with sanding debris
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Establish specification describing grit size for specific operations • Hand sand curved areas that require sanding • Repair die marks on mold, not on parts • Automate flash removal to eliminate error • Specify paper grit size for every repair method • Specify sandpaper change interval • Clean debris from unloading fixture or racks
<i>Tooling</i>	

Scratch

A scratch is similar to a gouge, but is not deep enough to require fill repair material. A scratch can usually be feather sanded out.

Probable Cause

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Rough handling • Improperly designed secondary fixtures (not padded in all necessary areas) • Mold defects on edges or flash stuck to shear edge • Shipping racks lack necessary padding • No use of in-process racks (parts are stacked on each other) • Square edge of part a mating surface with adjacent parts
<i>Tooling</i>	

Corrective Action

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Train workers in proper handling techniques • Design secondary fixtures properly and coat them with soft materials to absorb shocks • Design secondary fixtures properly and coat them with soft materials to absorb shocks • Preventative maintenance on molds and fixtures • Periodically clean flash on shear edge • Improve shipping procedure and monitor part quality • Improve shipping rack repair procedures • Utilize transfer lines and other hands-off processing techniques • Repair using approved repair procedure
<i>Tooling</i>	

Separation (Phasing)

An area of high thermoplastic content resulting in non-uniformity of color	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Separation of the thermoplastic resin from polyester
<i>Process</i>	
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Increase molding viscosity • Select different shrink additives and/or levels
<i>Process</i>	<ul style="list-style-type: none"> • Shorten die loading time • Increase material flow distance • Decrease molding pressure • Decrease molding temperature
<i>Tooling</i>	

Scumming

Dulling or streaks in the part (generally transfers a similar pattern on the tool surface).	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Incompatible resin additives
<i>Process</i>	<ul style="list-style-type: none"> • Internal mold release not functioning at the mold temperature
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Use greater viscosity material • Select different shrink additives and/or levels
<i>Process</i>	<ul style="list-style-type: none"> • Increase mold temperature • Increase material flow distance • Shorten tool loading time
<i>Tooling</i>	

Sink Marks

A sink is a depression on the part surface that will normally occur over ribs or bosses. It is possible to get a sink on the edge of a flanged part. Sinks can range in depth from 0.0004 to several thousands of an inch anywhere along a rib or boss.

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Poor glass orientation • Excess shrinkage of the SMC over a thick section
<i>Process</i>	<ul style="list-style-type: none"> • Inadequate molding pressure • Temperature variations due to variable thickness
<i>Tooling</i>	<ul style="list-style-type: none"> • Improper rib design

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Select different shrink additives and/or levels
<i>Process</i>	<ul style="list-style-type: none"> • Flow material from a thick section to a thin section so as not to create surge flow patterns in localized areas (the surge flow orients glass fibers perpendicular to adjacent areas which shows up as a sink). • Cross sectioning the wall section may be necessary to prove a thin-to-thick flow condition • Control aspect ratio of rib and boss (depth-to-thickness ratio); rib should not be more than 0.075" thickness of attached wall • Place ribs and bosses behind design lines • Mold off stops • If sink is over a "boss", reduce mass by having a long cored hole
<i>Tooling</i>	<ul style="list-style-type: none"> • Modify tooling

Sticking

Sticking occurs when the part adheres to the cavity or core and is not easily released or results in a crack upon removal.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Release problem with the SMC • SMC shrinkage control is incorrect
<i>Process</i>	<ul style="list-style-type: none"> • Core is too rough • Charge weight is excessive • Undercuts on cavity or core • Part is under-cured • Temperature spread on dies too close • Press strip is too fast • Contaminated mold surface (oils, dirt, etc)
<i>Tooling</i>	<ul style="list-style-type: none"> • Mold surface is corroded
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Check for SMC release • Check SMC shrinkage data
<i>Process</i>	<ul style="list-style-type: none"> • Slow strip speed • Clean mold surface/run break-in material • Add external mold release • Increase cycle time • Increase mold temperature
<i>Tooling</i>	<ul style="list-style-type: none"> • Evaluate mold for undercuts and remove where necessary • Check chrome plating wear • Polish tool surface • Pyramid charge in the center of the tool

Streaking (Abrasion)

Dark areas, directional, in line of flow, found in pigmented parts and is generally located over fiberglass strands	
Probable Cause	
<i>Material</i>	
<i>Process</i>	
<i>Tooling</i>	<ul style="list-style-type: none"> • Tool abrasion or scuffing
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Check raw material • Use greater viscosity material • Select different shrink additive or level
<i>Process</i>	<ul style="list-style-type: none"> • Relocate charge pattern
<i>Tooling</i>	<ul style="list-style-type: none"> • Polish or buff out tool surface • Chrome plate tool surface

Surface Waviness

Short term waviness has wave lengths for ¼ to one inch long. Long term waviness has wave lengths from one to five inches. Waviness causes distortion of straight lines on the Class “A” surface and is most readily observed on a painted part.

Probable Cause

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Improper spiral flow of SMC sheet when molded • Inconsistent force on the material during molding • Parts molded with improper pressure • Charge pattern cut or placed improperly • Flow interrupters (mash-offs, core pins, part geometry) in mold • Partial charge • Improper bonding temperature (Undercure) which can cause bond readout, causing waviness.
<i>Tooling</i>	

Corrective Action

<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Monitor spiral flow for appropriate values • Use proper pressure to mold material • Remove flow interrupters from mold • Monitor viscosity of paste • Monitor and control mold temperatures to specs • Refer to design guide for allowable thick-to-thin transition • Verify closure speeds, load pattern (location, size) and leveling • Verify molding off stops • Monitor viscosity of paste
<i>Tooling</i>	

Undercure

Undercure is an incomplete cure or bake cycle of the SMC in the mold. The part is often extremely smoky, very dull and can exhibit blown bosses or ribs. This part is scrapped.

Probable Cause

<i>Material</i>	<ul style="list-style-type: none"> • Unreactive resin • Incorrect cure chemistry
<i>Process</i>	<ul style="list-style-type: none"> • Low temperatures and/or short cycle time • Loss of tonnage
<i>Tooling</i>	

Corrective Action

<i>Material</i>	<ul style="list-style-type: none"> • Check SMC for cure time • Check resin reactivity
<i>Process</i>	<ul style="list-style-type: none"> • Check mold cold spots or bad stream lines and regulators • Verify cure times • Verify tonnage via parameter sheet
<i>Tooling</i>	

Warpage (Dimensional Error)

Dimensional error is the failure of the part to fit the checking fixture or to meet print tolerances due to Warpage, shrink, expansion or tooling error.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Out of spec material
<i>Process</i>	<ul style="list-style-type: none"> • Uneven cure • Excessive stress on the part when unloading or bonding • Not allowing the part to cool on fixture long enough • Variable charge pattern or placement • Improper expansion factor in tool for approved material • Improper thermal expansion material molded in approved mold • Improperly designed paint fixture • Degree of cure – bond line
<i>Tooling</i>	<ul style="list-style-type: none"> • Tool temperatures not within spec
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Verify SMC for proper shrinkage
<i>Process</i>	<ul style="list-style-type: none"> • Use heat management design of mold to permit consistent curing of part • Proper placement of ejector pins reduces demolding stress • Evaluate process for sufficient cooling time • Control charge pattern by area, not weight. When possible use laser light or automation to permit consistent charge placement • Design paint fixtures to properly support part during baking • If bonded assembly, review bonding process • Verify cure time versus tool temperature capability of maintaining correct temperature through consecutive moldings. • Decrease material flow distance • Increase cure time or temperature • Vary mold temperature differential • Increase charge pattern • Verify mold temperatures
<i>Tooling</i>	<ul style="list-style-type: none"> • Proper mold design to ensure that the part does not stick to core or cavity • Work with design engineers early in program so that mold is constructed using expansion factors of the newer-technology materials

Water Spots

Circular spots on the painted surface usually in groups. These spots are usually depressions with a raised ring around the edge. Water spots can cause paint failure of top coats/	
Probable Cause	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Failure to fully dry the part after a wash operation • Failure to use a DI water rinse after wash • Failure to clean and filter DI water to meet specifications • Part designs which trap water in pockets • Failure to use a rinse additive which ensures a water break-free surface
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	
<i>Process</i>	<ul style="list-style-type: none"> • Dry parts thoroughly after all wash operations • Design drain holes into parts when necessary to prevent the accumulation of water during the wash cycle • QC rinse water to specs • Use and maintain a rinse additive after parts washing
<i>Tooling</i>	

White Spots

A general light or whitened area on a pigmented surface that occurs as a result of thermoplastic separation. The problem is associated with pitting occurring in the white spotted area.	
Probable Cause	
<i>Material</i>	<ul style="list-style-type: none"> • Low viscosity builds of SMC through maturation • Thermoplastic incompatibility with SMC formulations • Flow restrictions
<i>Process</i>	
<i>Tooling</i>	
Corrective Action	
<i>Material</i>	<ul style="list-style-type: none"> • Verify day 1 viscosity • Record occurrence and roll yardage when problem occurs • Record material rates and lot number when problem occurs • Verify spiral flow of material
<i>Process</i>	<ul style="list-style-type: none"> • Verify load pattern is correct according to engineering specification • Reduce die coverage to allow for increased flow
<i>Tooling</i>	